
Subject: powernow-k8 problem with latest sles10 vz kernel

Posted by [dbeery](#) on Thu, 27 Sep 2007 03:57:41 GMT

[View Forum Message](#) <> [Reply to Message](#)

kernel-ovz-2.6.16.46_027test011-0.12.x86_64.rpm

quad AMD Opteron 8000 2.6GHz w/ 64GB RAM

and these types of messages are filling up my log:

powernow-k8: transition frequency failed

powernow-k8: vid trans failed, vid

powernow-k8: vid trans failed, fid

Not having any other problems so far but would like to get this fixed. Is there a patch or setting or something?

Derrick Beery

State of Iowa
