Subject: Re: DL380 G2 - CCISS
Posted by Vasily Tarasov on Fri, 16 Feb 2007 07:02:31 GMT

Hello,

Quote:
The steps taken when building this server:
- install CentOS 4.4 (minimal)
- Install Compaq SmartStart 7.7
- builds some drivers using the kernel sources
- Install OpenVZ:
- yum install ovzkernel-smp
- Throws: WARNING: No module cciss found for kernel 2.6.9-023stab040.1-smp, continuing anyway

There is a strange thing in your post. The step of "building some drivers using the kernel sources" goes before the step of "installing ovzkernel-smp". Drivers are always build against certain version of kernel. So, I guess, you should build them after ovz kernel is installed (and booted?)

However this doesn't explain the error...

Can you tell me, please, does CentOS 4.4 kernel with no additional drivers boot normally?

Thanks.