Subject: Re: No module 3w-9xxx found for kernel 2.6.18-ovz028stab047.1-smp
Posted by ugob on Thu, 25 Oct 2007 18:21:19 GMT

I think that the driver is in the kernel. I have a server with a 8006LP. If you can afford to reboot and maybe have a server down, go ahead and reboot, you'll see.

If you're not close to the server or if it is mission-critical, please wait for a confirmation of a member of the openvz team.