Subject: Re: Problem Inserting Microcode (Wrong arch?)
Posted by tomp on Mon, 03 Dec 2007 22:33:38 GMT

Hi

I am in the identical situation to you. I too have a Dell 1950 server with nothing installed except the ovz kernel and Dell openmanage software all installed via yum.

If i insmod the microcode module from the x64 lib folder then there are no errors when i run modprobe microcode. However running the command by itself generates the same errors as appear on boot.