Subject: Re: SCSI DPT vs I2O problems [was: Will development now move to 2.6.16?]
Posted by khorenko on Fri, 21 Apr 2006 09:45:18 GMT
View Forum Message <> Reply to Message

mephisto, as vaverin have already said we had faced issues that i2o_block and dpt_i2o drivers do not work properly in 2.6.8 kernel if compiled into the kernel.

Please, could you build a 2.6.8 OpenVZ kernel with _disabled_ CONFIG_I2O option and CONFIG_SCSI_DPT_I2O=m (message #2135)?

Yes, in that case you should create initrd file to boot, but it looks like this is the only possible way to make dpt_i2o driver working in 2.6.8 kernel.