Subject: Re: two NICs in openvz
Posted by maratrus on Tue, 10 Mar 2009 07:52:10 GMT

Hello,

this is not OpenVZ problem
according to http://hardware4linux.info/component/8137/
this driver is included in kernels >= 2.6.21
but 2.6.18-92.1.18.el5.028stab060.2 is based on
2.6.18 RHEL5 kernels.

I didn't manage to find sources for RHEL5 2.6.18 kernels.

Then I tried sources for altlinux
 http://ftp.altlinux.org/pub/people/vsu/sc92031/x86_64/RPMS.h asher/

I installed kernel-devel package for OpenVZ kernel,
and extracted sc92031.c from kernel-source-sc92031-2.0c-alt1.noarch.rpm
The only change I made is
"#if LINUX_VERSION_CODE < KERNEL_VERSION(2,6,18)".
Driver is compiled but I have no chance to check if it's workable.
I attached source, binary files and Makefile just in case.

File Attachments
1) sc92031.c, downloaded 317 times
2) sc92031.ko, downloaded 213 times
3) Makefile, downloaded 259 times