Subject: Re: Problems booting ovzkernel-2.6.8-022stab045.1
Posted by vaverin on Sat, 17 Dec 2005 07:47:25 GMT
View Forum Message <> Reply to Message

Sehr geehrter Herr Fischer,
mintra,

It seems I'm understand the cause of your troubles:
in .45 kernel we have moved support for SATA controller with PCI ID 8086:2652 and 8086:2653
from ata_piix subdriver to ahci subdriver.
However due misprinting we have not enabled the compilation of ahci subdriver in our kernels.

Looks like you have mentonied SATA controllers, and the boot is failed because of our .45 and
.50 kernels have not support for these devices.

This error is fixed already and we're going to release new kernel soon.

Thank you for your bugreports,
        Vasily Averin