Subject: Re: 2.6.20.12-ovz007.1 on AMD X2 AM2: cpufreq does not change freq
Posted by ugo123 on Tue, 03 Jul 2007 13:19:27 GMT
View Forum Message <> Reply to Message

You may have the same problem that I have with my cheap motherboard and recent Linux kernels....

Check your dmesg if you have something like

powernow-k8: MP systems not supported by PSB BIOS structure
powernow-k8: MP systems not supported by PSB BIOS structure

That's my problem for about a year and I don't a real answer since then.....