Subject: powernow-k8 problem with latest sles10 vz kernel
Posted by dbeery on Thu, 27 Sep 2007 03:57:41 GMT
View Forum Message <> Reply to Message

kernel-ovz-2.6.16.46_027test011-0.12.x86_64.rpm
quad AMD Opteron 8000 2.6GHz w/ 64GB RAM

and these types of messages are filling up my log:

powernow-k8: transition frequency failed
powernow-k8: vid trans failed, vid
powernow-k8: vid trans failed, fid

Not having any other problems so far but would like to get this fixed. Is there a patch or setting or something?

Derrick Beery
State of Iowa