Posted by sHaggY_caT on Sun, 09 Nov 2008 01:38:44 GMT
View Forum Message <> Reply to Message

[shaggycat@hn SOURCES]$ cat /etc/redhat-release
CentOS release 5.2 (Final)
[shaggycat@hn SOURCES]$ uname -a
Linux hn.loc 2.6.18-92.1.1.el5.028stab057.2 #1 SMP Mon Jul 21 20:55:45 MSD 2008 i686 i686 i386 GNU/Linux
[shaggycat@hn SOURCES]$ rpm -qa | grep vz | grep -v vztmpl
ovzkernel-2.6.18-92.1.1.el5.028stab057.2
vzrpm44-4.4.1-22.5
vzrpm43-python-4.3.3-7_nonptl.6
vzdump-1.0-2
ovzkernel-devel-2.6.18-92.1.1.el5.028stab057.2
vzctl-lib-3.0.22-1
vzctl-3.0.22-1
vzyum-2.4.0-11
vzrpm44-python-4.4.1-22.5
vzrpm43-4.3.3-7_nonptl.6
vzquota-3.0.11-1
vzpkg-2.7.0-18
[shaggycat@hn SOURCES]$

[shaggycat@hn SOURCES]$ lspci -v | grep -A 4 "Atheros Communications Inc"
01:09.0 Ethernet controller: Atheros Communications Inc. AR5212/AR5213 Multiprotocol MAC/baseband processor (rev 01)
	Subsystem: D-Link System Inc D-Link AirPlus DWL-G520 Wireless PCI Adapter(rev.B)
	Flags: medium devsel, IRQ 225
	Memory at f9000000 (32-bit, non-prefetchable) [disabled] [size=64K]
	Capabilities: <access denied>
[shaggycat@hn SOURCES]$

```
 ======================
ieee80211_unref_node: NULL ieee80211_node *
 [<f8b65180>] ieee80211_input+0x165e/0x1676 [wlan]
 [<f9673724>] ath_intr+0xbbe/0x236e [ath_pci]
 [<f8b7a2cb>] ieee80211_input_monitor+0x10f/0x72b [wlan]
 [<f8b65210>] ieee80211_input_all+0x78/0x9a [wlan]
 [<f966aec6>] ath_rx_tasklet+0x6e7/0x9d8 [ath_pci]
 [<c0427577>] tasklet_action+0x5b/0xb5
 [<c04271aa>] __do_softirq+0x84/0x109
 [<c0427265>] do_softirq+0x36/0x3a
 [<c0406583>] do_IRQ+0xad/0xb6
 [<c060b2ae>] common_interrupt+0x1a/0x20
 [<c0403c5d>] default_idle+0x0/0x59
 [<c0403c8e>] default_idle+0x31/0x59
 [<c0403d14>] cpu_idle+0x5e/0x74
 [<c0742c08>] start_kernel+0x397/0x39e
 ======================
wifi0: ath_bstuck_tasklet: Stuck beacon; resetting (beacon miss count: 11)
ath0: no IPv6 routers present



ACPI: PCI interrupt for device 0000:01:09.0 disabled
AR5210, AR5211, AR5212, AR5416, RF5111, RF5112, RF2413, RF5413, RF2133)
ath_pci: disagrees about version of symbol ieee80211_check_mic
ath_pci: Unknown symbol ieee80211_check_mic
ath_pci: disagrees about version of symbol ieee80211_encap
ath_pci: Unknown symbol ieee80211_encap
ath_pci: disagrees about version of symbol ieee80211_input
ath_pci: Unknown symbol ieee80211_input
ath_pci: disagrees about version of symbol ieee80211_ifattach
ath_pci: Unknown symbol ieee80211_ifattach
ath_pci: disagrees about version of symbol ieee80211_beacon_update
ath_pci: Unknown symbol ieee80211_beacon_update
```

ath_pci: disagrees about version of symbol ieee80211_find_rxnode
ath_pci: Unknown symbol ieee80211_find_rxnode
ath_pci: disagrees about version of symbol ieee80211_ref_node
ath_pci: Unknown symbol ieee80211_ref_node
ath_pci: disagrees about version of symbol ieee80211_vap_setup
ath_pci: Unknown symbol ieee80211_vap_setup
ath_pci: disagrees about version of symbol ieee80211_ifdetach
ath_pci: Unknown symbol ieee80211_ifdetach
ath_pci: disagrees about version of symbol ieee80211_input_monitor

http://sisyphus.ru/releases?tid=232