

---

Subject: Re: 3Ware 8006-2LP

Posted by [khorenko](#) on Fri, 20 Jul 2007 08:33:22 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

well, it looks i find the root of the problem:

<http://www.ussg.iu.edu/hypermail/linux/kernel/0409.2/1833.ht ml>

Quote:The /proc/scsi interface is being deprecated by the SCSI subsystem maintainers.

Support for /proc/scsi/3w-xxxx has been removed from the driver and sysfs support has been added. Please download the newer 3dm2 tools from the 3ware software "In-Engineering Development" website, or, keep your older kernel and tools.

Hope 3dm2 will help.

P.S. sorry, this might was not clear - the above words were not mine, this was a quotation from the link.

---