
Subject: Re: e1000e device eth0 does not seem to be found

Posted by [dschauer](#) on Fri, 24 Apr 2009 00:39:10 GMT

[View Forum Message](#) <> [Reply to Message](#)

I had the same problem with both 2.6.27-aivazovsky.1 and 2.6.27-briullov.1

I made the following patches that I apply before building:

[http://aur.archlinux.org/packages/kernel26-openvz-das/kernel 26-openvz-das/e1000e_hw.h.patch](http://aur.archlinux.org/packages/kernel26-openvz-das/kernel%2026-openvz-das/e1000e_hw.h.patch)

[http://aur.archlinux.org/packages/kernel26-openvz-das/kernel
26-openvz-das/e1000e_netdev.c.patch](http://aur.archlinux.org/packages/kernel26-openvz-das/kernel%2026-openvz-das/e1000e_netdev.c.patch)
