

---

Posted by [urodliv](#) on Wed, 17 Oct 2012 20:23:34 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Linux ovz 2.6.32-5-openvz-686 #1 SMP Sun Sep 23 11:40:07 UTC 2012 i686 GNU/Linux

00:0e.0 Ethernet controller: Intel Corporation 82557/8/9/0/1 Ethernet Pro 100 (rev 08)

00:10.0 Ethernet controller: 3Com Corporation 3c905C-TX/TX-M [Tornado] (rev 78)

00:12.0 Ethernet controller: 3Com Corporation 3c905B 100BaseTX [Cyclone] (rev 64)

00:13.0 Ethernet controller: Intel Corporation 82557/8/9/0/1 Ethernet Pro 100 (rev 08)

00:14.0 Ethernet controller: Realtek Semiconductor Co., Ltd. RTL-8029(AS)

ii firmware-linux 0.28+squeeze1 Binary firmware for various drivers in the Linux kernel (meta-package)

ii firmware-linux-free 2.6.32-46 Binary firmware for various drivers in the Linux kernel

ii firmware-linux-nonfree 0.28+squeeze1 Binary firmware for various drivers in the Linux kernel

Oct 18 00:08:26 ovz kernel: [ 3428.789663] e100 0000:00:13.0: firmware: requesting e100/d101m\_ucose.bin

Oct 18 00:09:26 ovz kernel: [ 3488.788163] e100: eth0: e100\_request\_firmware: Failed to load firmware "e100/d101m\_ucose.bin": -2

---