

---

Subject: Re: i2o hardware hangs (ASR-2010S)  
Posted by [Markus Lidel](#) on Mon, 07 Aug 2006 09:23:16 GMT  
[View Forum Message](#) <> [Reply to Message](#)

---

Hello,

Salyzyn, Mark wrote:

> Markus, when the commands time out, do you perform a reset iop sequence?

Currently not.

> I thought you added the BlinkLED code detection that is in the dpt\_i2o  
> driver, if not, we should make sure it is there so that we get a report  
> in the console and an accompanying reset. Vasily, you console log did  
> not report anything at the time of failure, I would have expected some  
> timeout reports.

I agree, there should be some notice that a command timed out.

[...]

>> Described incident has occurred after ~2 weeks uptime. It was  
>> Supermicro X5DP8  
>> motherboard /8Gb memory /Adaptec ASR-2010S I2O Zero Channel. Kernel  
>> 2.6.8-022stab078.9-enterprise, sources/configs are accessible  
>> on [openvz.org](http://openvz.org).

Could you please try out a current kernel?

Best regards,

Markus Lidel

-----  
Markus Lidel (Senior IT Consultant)

Shadow Connect GmbH  
Carl-Reisch-Weg 12  
D-86381 Krumbach  
Germany

Phone: +49 82 82/99 51-0  
Fax: +49 82 82/99 51-11

E-Mail: [Markus.Lidel@shadowconnect.com](mailto:Markus.Lidel@shadowconnect.com)  
URL: <http://www.shadowconnect.com>

---