
Subject: Re: i2o hardware hangs (ASR-2010S)
Posted by [Markus Lidel](#) on Mon, 07 Aug 2006 09:23:16 GMT
[View Forum Message](#) <> [Reply to Message](#)

Hello,

Salyzyn, Mark wrote:

> Markus, when the commands time out, do you perform a reset iop sequence?

Currently not.

> I thought you added the BlinkLED code detection that is in the dpt_i2o
> driver, if not, we should make sure it is there so that we get a report
> in the console and an accompanying reset. Vasily, you console log did
> not report anything at the time of failure, I would have expected some
> timeout reports.

I agree, there should be some notice that a command timed out.

[...]

>> Described incident has occurred after ~2 weeks uptime. It was
>> Supermicro X5DP8
>> motherboard /8Gb memory /Adaptec ASR-2010S I2O Zero Channel. Kernel
>> 2.6.8-022stab078.9-enterprise, sources/configs are accessible
>> on openvz.org.

Could you please try out a current kernel?

Best regards,

Markus Lidel

Markus Lidel (Senior IT Consultant)

Shadow Connect GmbH
Carl-Reisch-Weg 12
D-86381 Krumbach
Germany

Phone: +49 82 82/99 51-0
Fax: +49 82 82/99 51-11

E-Mail: Markus.Lidel@shadowconnect.com
URL: <http://www.shadowconnect.com>
