Subject: Re: OpenVZ container network speeds Posted by ccto on Sun, 26 Jan 2014 13:07:30 GMT

View Forum Message <> Reply to Message

I also have a similar motherboard (Intel Server board), it runs RHEL 6.3, the attached 82574L will crash the server (probably under high network traffic load).

You may try to apply some ROM patch http://sourceforge.net/projects/e1000/files/e1000e%20stable/ eeprom_fix_82574_or_82583/

But my final solution: use 82579?? for high traffic NIC instead.