
Subject: **** SOLVED **** e1000e device eth0 does not seem to be found

Posted by [slonghurst](#) on Thu, 23 Apr 2009 10:27:49 GMT

[View Forum Message](#) <> [Reply to Message](#)

Hi

I am trying to do a new install of openvz on a centos5.3 server. I have installed

ovzkernel.i686 2.6.188-92.1.18.el5.028stab060.8

When i reboot into openvz i get an error when starting networking

e1000e device eth0 does not seem to be found

ifconfig shows only the loopback interface

lsmod showed that e1000e is loaded.

modprobe.conf shows "alias eth0 e1000e"

dmesg | grep eth0 gave zero output

modprobe -r eth0 and then modprobe eth0 with no success

i have attached output of dmesg, lspci and lspci -n

as always help greatly appreciated.

Regards

Shaun

File Attachments

- 1) [dmesg_output.txt](#), downloaded 420 times
 - 2) [lspci_output.txt](#), downloaded 385 times
 - 3) [lspci_n_output.txt](#), downloaded 386 times
-

Subject: Re: e1000e device eth0 does not seem to be found

Posted by [cgm00](#) on Thu, 23 Apr 2009 16:05:48 GMT

[View Forum Message](#) <> [Reply to Message](#)

I had same issue and my solution was to compile
last e1000e driver (e1000e-0.5.18.3.tar.gz)

```
#rpm -Uhv ovzkernel-devel-2.6.18-92.1.18.el5.028stab060.8.x86_64.rpm
```

```
# cd e1000e-0.5.18.3/src/
```

```
# BUILD_KERNEL=2.6.18-92.1.18.el5.028stab060.8 make
```

```
then copy the e1000e.ko to /lib/modules/..
```

```
(in my case /lib/modules/2.6.18-92.1.18.el5.028stab060.8/kernel/drivers/ net/e1000e/e1000e.ko)
```

```
reboot.. that should do it
```

make sure you do that for each OVZ kernel update till this is fixed

Subject: Re: e1000e device eth0 does not seem to be found

Posted by [dschauer](#) on Fri, 24 Apr 2009 00:39:10 GMT

[View Forum Message](#) <> [Reply to Message](#)

I had the same problem with both 2.6.27-aivazovsky.1 and 2.6.27-briullov.1

I made the following patches that I apply before building:

http://aur.archlinux.org/packages/kernel26-openvz-das/kernel-26-openvz-das/e1000e_hw.h.patch
http://aur.archlinux.org/packages/kernel26-openvz-das/kernel-26-openvz-das/e1000e_netdev.c.patch

Subject: Re: e1000e device eth0 does not seem to be found

Posted by [slonghurst](#) on Fri, 24 Apr 2009 07:21:02 GMT

[View Forum Message](#) <> [Reply to Message](#)

compiling the drivers worked a treat.

Thanks

Shaun
