

---

Subject: Re: system time problems with ovz kernels

Posted by [dev](#) on Tue, 06 Dec 2005 09:25:20 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Please, provide the following information to help to resolve it:

1. during the boot kernel selects the timesource, check for string like this:

Using ... for high-res timesource

what timesource is used in 038 and in 045/050?

2. does kernel boot parameter "clock=pit" helps?

and "clock=tsc"?

3. I suppose this happened due to turned ON ACPI. Are you able to build and check kernel with options changes I will provide you?

---