
Subject: Re: OVZ Kernels and e1000 nic
Posted by [khorenko](#) on Fri, 23 Mar 2007 09:33:05 GMT
[View Forum Message](#) <> [Reply to Message](#)

dev wrote on Fri, 23 March 2007 03:41
Is your NIC works fine with CentOS4 kernel?
actually OVZ 2.6.9 kernel is almost the same... So I wonder, what's the problem you face...

And considering this: do you know if any additional drivers were installed on the node to make CentOS working? Might be a newer e1000 driver?

You can check this by commands:

```
# rpm -q kernel
```

```
kernel-2.6.9-34.EL
```

```
# rpm -V kernel-2.6.9-34.EL
```

```
...
```

if some modules were changed rpm should determine this.
