

---

Subject: Re: 2.6.20.12-ovz007.1 on AMD X2 AM2: cpufreq does not change freq  
Posted by [tobbi](#) on Tue, 03 Jul 2007 14:01:47 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Thank you for your kind answer Ugo, but that's not it.

With vanilla 2.6.22 and a very similar kernel .config (difference only due to different kernel version and missing openvz), cpufreq runs fine on that machine.

Wait, now that I think about it, I should try 2.6.20.12 vanilla as well. But cpufreq and the powernow3d-k8 driver worked fine with 2.6.16 and 2.6.18 on an ECS Elite mainboard with AMD Athlon64 X2 4200+ on socket 939, which is not too far off. Hence I assume that vanilla kernels are all fine since 2.6.16 or earlier, and that my problem has something to do with the ovz007.1 patch.

Have a good time...

---