Subject: Re: Will development now move to 2.6.16? Posted by vaverin on Tue, 21 Mar 2006 06:50:42 GMT

View Forum Message <> Reply to Message

Hello mephisto,

Unfortunately I cannot understand what kind of problem you have on the node.

As far as I see from your Ispci, you have I2O zero-channel raid controller. It supported by our kernel and your node should work even on the 2.6.8 kernel.

To load our kernel on this hardware you should create correct initrd image. Could you please send me /etc/modprobe.conf file and

output of the following command

mkinitrd -v -v -f /boot/custom.initrd.img 2.6.8-022stab070.1

thank you, Vasily Averin

PS could you probably give me an access to the node?