

---

Subject: Re: Device eth0 has different MAC address than expected

Posted by [dev](#) on Sat, 08 Apr 2006 19:04:20 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

vz10b4, I uploaded 076 kernel build for you to:

<http://download.openvz.org/~dev/076/>

can you please check that your issue with e1000 is solved?

---