
Subject: Re: VE: 102: failed to start with err=-17
Posted by [yettyn](#) on Fri, 11 Jan 2008 21:20:58 GMT
[View Forum Message](#) <> [Reply to Message](#)

hmm something must be really wrong as not even if I plugin a 3Com905C and load the driver eth0 exist, only lo - really wired. lspci sees it though so hw must be functional and I been over the config and can't see anything missing or that shouldn't be there. Anyone have an idea what can cause such thing?
