Subject: Re: two NICs in openvz Posted by maratrus on Tue, 10 Mar 2009 07:52:10 GMT

View Forum Message <> Reply to Message

Hello,

this is not OpenVZ problem according to http://hardware4linux.info/component/8137/this driver is included in kernels >= 2.6.21 but 2.6.18-92.1.18.el5.028stab060.2 is based on 2.6.18 RHEL5 kernels.

I didn't manage to find sources for RHEL5 2.6.18 kernels.

Then I tried sources for altlinux http://ftp.altlinux.org/pub/people/vsu/sc92031/x86\_64/RPMS.h asher/

I installed kernel-devel package for OpenVZ kernel, and extracted sc92031.c from kernel-source-sc92031-2.0c-alt1.noarch.rpm The only change I made is "#if LINUX\_VERSION\_CODE < KERNEL\_VERSION(2,6,18)". Driver is compiled but I have no chance to check if it's workable. I attached source, binary files and Makefile just in case.

## File Attachments

- 1) sc92031.c, downloaded 288 times
- 2) sc92031.ko, downloaded 202 times
- 3) Makefile, downloaded 238 times