
Subject: Re: Intel e1000e driver for 2.6.18-ovz
Posted by [maratrus](#) on Fri, 07 May 2010 12:59:49 GMT
[View Forum Message](#) <> [Reply to Message](#)

Hello,

as you may notice the compiler complains about redefinition of `irq_handler_t`. This type has already been defined in `include/linux/interrupt.h` but the driver contains redundant definition in `/usr/src/e1000e-1.1.2.1a/src/kcompat.h`. So you have properly avoid such a coincidence. Look carefully why `kcompat.h` contains such a definition. It might be `"#ifdef"` constructions or something else.
