
Subject: Debian lenny to 2.6.32-5 kernel network
Posted by [alexlp](#) on Fri, 31 Dec 2010 08:35:14 GMT
[View Forum Message](#) <> [Reply to Message](#)

I've updated my lenny 2.6.26-1-openvz-686 to squeeze kernel 2.6.32-5-openvz-686.

There are 3 networking cards at my PC:

D-Link System Inc RTL8139 Ethernet (rev 10)
Realtek Semiconductor Co., Ltd. RTL-8169 Gigabit Ethernet (rev 10)
Intel Corporation 82574L Gigabit Network Connection

8139 works fine, but gigabit-cards "down" after system boots:
if I start to ping, after 60 packets I'm loosing ping. But in arp -a, I've see network MAC's of the plugged network.

Is any solution to fix it?
