
Subject: Re: Tasks hanging cause node to reboot/stall

Posted by [bjdea1](#) on Sat, 24 Sep 2011 23:47:06 GMT

[View Forum Message](#) <> [Reply to Message](#)

I'm currently seeing a similar issue on RHEL 6 kernel (all of them). I get a random process soft_locking the CPU, using 100% and node load spikes to over 1000 and I lose control of node. This happens on 2 servers, the only 2 servers I am running RHEL6. I'm wondering if my servers have hardware issues, but both have the exact same issue so I'm thinking its more likely to be a driver issue, or something else in the kernel. I'm running 2 Dell 1950 III servers - pretty common mainstream servers.
