

---

Subject: Re: Intel e1000e Driver Bug  
Posted by [Electron](#) on Fri, 24 Feb 2012 10:21:48 GMT  
[View Forum Message](#) <> [Reply to Message](#)

---

We was fixed bug with update driver for NIC from elrepo.org and write to boot kernel keys instant off of power management of pcie :

pcie\_aspm=off

---