
Subject: Re: [Q] ide cdrom in native mode leads to irq storm?

Posted by [Alan Cox](#) on Fri, 27 Oct 2006 14:19:39 GMT

[View Forum Message](#) <> [Reply to Message](#)

Ar Gwe, 2006-10-27 am 17:17 +0400, ysgrifennodd Vasily Averin:

> Could somebody please help me to troubleshoot this issue? I've seen this issue
> on the customer nodes and would like to know how I can work-around this issue
> without any changes inside motherboard BIOS.

If its an IRQ routing triggered problem you probably can't, at least not the IDE error. The oops wants debugging further because it shouldn't have oopsed on that error merely given up.
