
Subject: PCI: Bridg

Posted by [cheitac](#) on Thu, 01 Mar 2012 07:06:20 GMT

[View Forum Message](#) <> [Reply to Message](#)

Hi All!

after server upgrade I find some errors in dmesg. is it bug or something like that?

#uname -r

2.6.18-274.18.1.el5.028stab098.1

#dmesg

"

PCI: Bridge: 0000:00:01.0

IO window: disabled.

MEM window: disabled.

PREFETCH window: disabled.

PCI: Bridge: 0000:00:05.0

IO window: disabled.

MEM window: disabled.

PREFETCH window: disabled.

PCI: Bridge: 0000:06:00.0

IO window: disabled.

MEM window: disabled.

PREFETCH window: disabled.

PCI: Bridge: 0000:05:00.0

IO window: disabled.

MEM window: disabled.

PREFETCH window: disabled.

PCI: Bridge: 0000:05:00.3

IO window: disabled.

MEM window: disabled.

PREFETCH window: disabled.

PCI: Bridge: 0000:00:09.0

IO window: disabled.

MEM window: fde00000-fdefffff

PREFETCH window: disabled.

PCI: Bridge: 0000:00:1c.0

IO window: disabled.

MEM window: fcb00000-fdbfffff

PREFETCH window 0x00000000faa00000-0x00000000fc9fffff

PCI: Bridge: 0000:00:1c.1

IO window: disabled.

MEM window: fdc00000-fdcfffff

PREFETCH window: disabled.

PCI: Bridge: 0000:00:1c.2

IO window: disabled.

MEM window: fdd00000-fddfffff
PREFETCH window: disabled.
PCI: Bridge: 0000:00:1e.0
IO window: disabled.
MEM window: disabled.
PREFETCH window: disabled.
GSI 16 sharing vector 0xA9 and IRQ 16
ACPI: PCI Interrupt 0000:00:01.0[A] -> GSI 48 (level, low) -> IRQ 169
PCI: Setting latency timer of device 0000:00:01.0 to 64
GSI 17 sharing vector 0xB1 and IRQ 17
ACPI: PCI Interrupt 0000:00:05.0[A] -> GSI 52 (level, low) -> IRQ 177
PCI: Setting latency timer of device 0000:00:05.0 to 64
GSI 18 sharing vector 0xB9 and IRQ 18
ACPI: PCI Interrupt 0000:00:09.0[A] -> GSI 56 (level, low) -> IRQ 185
PCI: Setting latency timer of device 0000:00:09.0 to 64
GSI 19 sharing vector 0xC1 and IRQ 19
ACPI: PCI Interrupt 0000:05:00.0[A] -> GSI 16 (level, low) -> IRQ 193
PCI: Setting latency timer of device 0000:05:00.0 to 64
PCI: Setting latency timer of device 0000:06:00.0 to 64
PCI: Setting latency timer of device 0000:05:00.3 to 64
ACPI: PCI Interrupt 0000:00:1c.0[A] -> GSI 16 (level, low) -> IRQ 193
PCI: Setting latency timer of device 0000:00:1c.0 to 64
GSI 20 sharing vector 0xC9 and IRQ 20
ACPI: PCI Interrupt 0000:00:1c.1[B] -> GSI 17 (level, low) -> IRQ 201
PCI: Setting latency timer of device 0000:00:1c.1 to 64
GSI 21 sharing vector 0xD1 and IRQ 21
ACPI: PCI Interrupt 0000:00:1c.2[C] -> GSI 18 (level, low) -> IRQ 209
PCI: Setting latency timer of device 0000:00:1c.2 to 64
PCI: Setting latency timer of device 0000:00:1e.0 to 64
NET: Registered protocol family 2
IP route cache hash table entries: 131072 (order: 8, 1048576 bytes)
TCP established hash table entries: 262144 (order: 10, 4194304 bytes)
TCP bind hash table entries: 65536 (order: 8, 1048576 bytes)
TCP: Hash tables configured (established 262144 bind 65536)
TCP reno registered
UDP bind hash table entries: 32768 (order: 7, 524288 bytes)
audit: initializing netlink socket (disabled)
type=2000 audit(1330596689.991:1): initialized
Total HugeTLB memory allocated, 0
"

File Attachments

1) [dmesg.txt](#), downloaded 403 times
