
Subject: Re: Device eth0 has different MAC address than expected

Posted by [vz10b4](#) on Tue, 04 Apr 2006 17:44:27 GMT

[View Forum Message](#) <> [Reply to Message](#)

Hi again,

Did install a 3com 3c905C-TX that works and is recognized by kudzu under the openvz kernel and the RHEL4 kernel. I configured it as eth0 but my eth1, Intel 82573L Gigabit NIC, still has the same problems when booting the openvz kernel. Kudzu does not even find that NIC after I removed it from the configuration.

I do not know if this helps to solve this issue but I will continue with the trial and error and I am stubborn as a blue pig:-)

Kind Regards
Fredrik
